



No. 21 - 2308-10 Routh

Approx. 1910-20

Description: Craftsman, hip roof with large gablet, central chimney, 9/1 windows, 2 gable porch roof extensions with hiplets, heavy square porch posts, wide plain trim, paired front windows, original wood porch and stairs.

Condition: Excellent.



No. 22 - 2500 State

Approx. 1890-95

Description: Queen Anne Victorian, steep pyramid roof with intersecting gable, gable dormer, large bay, cornice window heads, 1/1 windows, ornate gable trim, ornate knee braces from bay to gable.

Condition: Excellent - restored.



No. 23 - 2504 State

Approx. 1910-20;

Description: Bungalow, gable roof, smaller gable porch roof, exposed rafter ends, 4 round porch posts, 1/1 windows with wide trim, angle brackets and braces to support projecting eaves, original wood porch.

Condition: Fair - covered.



No. 24 - 2508-10 State

Approx. 1910-15;

Description: Craftsman, 2 story, gable roof with intersecting porch gable, 3 first floor doors, 2 second floor doors to balcony, 6/6 windows with wide trim, square porch posts, wood porch.

Condition: Fair.



No. 25 - 2512 State

Approx. 1890-1900;

Description: Planbook, pyramid roof inset front porch, deep cornice, 1/1 windows, grill work porch posts, boxed eaves.

Condition: Good



No. 26 - 2600 State

Approx. 1885-90

Description: Italianate, 2 story, pyramid roof, large hip dormer, intersecting gable with bay pavilion, extended eaves with brackets every 12", tall 1/1 windows with cornice window heads, ornate knee brackets at gable, transom corner and sidelights.

Condition: Excellent.



No. 27 - 2606 State

Approx. 1890-95;

Description: Eastlake, main gable with hiplet, large projecting bay with gable, hip porch roof, large gable dormer, 1/1 windows with cornice window heads, side and back chimneys, stain glass in bay and gable end, transom; Doric porch columns, brackets every 1 to 2 feet, ornate bay knee braces.

Condition: Excellent.



No. 28 - 2608 State

Approx. 1900-10;  
Description: Craftsman, 2 story, hip roof with shed porch roof, deep cornice at porch, heavy square porch columns, 8/8, 1/1 windows, exposed rafter ends, narrow lap siding, wide trim boards.  
Condition: Excellent - restored.





No. 29 - 2612 State

Approx. 1905-15;

Description: hip roof with 2 gable porch roof projections, extended eaves, exposed rafters, narrow lap siding, 1/1 windows, wide trim boards.

Condition: Good-excellent.



No. 30 - 2616 State

Approx. 1890-95

Description: Victorian planbook, intersecting gable roofs, shed porch roof with small pediment, gable dormer, Greek Revival pediment window heads, 1/1 narrow windows, transom, corner and sidelights with pediment, Doric porch columns, on brick piers, lap siding.

Condition: Fair.