

City of Dallas
Landmark Commission
Junius Heights Special Meeting
TASK FORCE MEETING

RECORDED
2007 DEC 10 AM 8:16
CITY SECRETARY
DALLAS, TEXAS

REVISED

Thursday, December 13, 2007

Meeting Location: **Lakewood Library 6121 Worth Street**

Time: **5:30 pm**

1. 5522 Worth - Rear Addition.
2. 5917 Reiger - Move back the front face of the existing non-original front dormer about 3 feet. Change the materials, roof form and windows of this dormer. Paint entire structure. Change out windows to be six –over-six. Remove the enclosed portion of the rear second story porch and change the hip roof to a gable. Change windows on this dormer also. Repair and replace rotten and damaged wood throughout the structure, replace the existing gutters with new gutters.
3. 5519 Worth – Explore front window configuration. Aluminum windows have been installed on the front façade. New front porch columns if the original columns are not under that brick added in the past.
4. 718 Parkmont - Revise window, located in side gable, from original design. New window is required for building code egress.
5. 5637 Worth - Fence