

# Memorandum



Date: May 29, 2009

To: Dr. Elba Garcia, Chair  
and Members of the Public Safety Committee

Subject: Fire Reports

The Public Safety Committee will be briefed on the Fire Reports on Monday, June 1, 2009.



Ryan S. Evans  
First Assistant City Manager

## Attachment

c: Honorable Mayor and Members of the Dallas City Council  
Mary K. Suhm, City Manager  
Deborah Watkins, City Secretary  
Tom Perkins, City Attorney  
Craig Kinton, City Auditor  
Victor Lander, Administrative Municipal Judge  
Ramon F. Miguez, P.E., Assistant City Manager  
Jill A. Jordan, P.E., Assistant City Manager

# Public Safety Committee

## Fire Report

April/May 2009

DATE	ADDRESS	COUNCIL DISTRICT	TYPE	CAUSE	LOSS/INSURED?	ALARMS
1. 03/26/09	8080 Leigh Ann Drive	8 District	2-Story Brick Apartments	Careless Use of Electric Cook Stove	\$17,500.00 Yes	2 Alarms
2. 03/29/09	2842 Britton Avenue	4 District	1-Story Frame Dwelling	Careless use of Candles	\$50,500.00 No	1 Alarm <b>(Fatality)</b>
3. 03/30/09	5606 Arlington Park Drive	2 District	1-Story Frame Dwelling	Unspecified Electrical Short Circuit (Appliance) <b><u>Smoke Detector Save</u></b>	\$6,000.00 Unknown	1 Alarm
4. 04/03/09	5921 Harvest Hill Road #2087	13 District	2-Story Stucco Condominiums	Unspecified Electrical Short Circuit (Fixed Wiring)	\$217,000.00 Yes	3 Alarms
5. 04/04/09	3132 Norwalk Avenue #312	6 District	3-Story Stucco Apartments	Careless Smoking	\$9,000.00 No	2 Alarms
6. 04/07/09	5930 Arapaho Road #2003	11 District	2-Story Frame Apartments	Combustibles Too Close To Heat Source	\$763,500.00 Yes	3 Alarms
7. 04/20/09	1321 Commerce Street	14 District	24-Story Brick Hotel	Unspecified Mechanical Malfunction (Gas Clothes Dryer) <b><u>Smoke Detector Save</u></b>	\$6,000.00 Yes	3 Alarms
8. 04/26/09	1636 W. Mockingbird Lane	2 District	1-Story Tilt Wall Commercial	Unspecified Electrical Short Circuit (Fixed Wiring)	\$110,000.00 Yes	2 Alarms
9. 05/03/09	4950 Wadsworth Drive #2089	5 District	2-Story Frame Apartments	Incendiary	\$200,000.00 Yes	4 Alarms
10. 05/04/09	5220 Duncanville Road	3 District	1-Story Masonry Commercial	Unspecified Electrical Short Circuit (Fixed Wiring)	\$110,000.00 Yes	2 Alarms
11. 05/04/09	3916 Clover Lane	13 District	1-Story Brick Dwelling	Incendiary	\$165,000.00 Yes	1-Alarm <b>(Injury)</b>
12. 05/10/09	5909 Birchbrook Drive #214	14 District	2-Story Brick Condominiums	Unspecified Electrical Short Circuit (Fixed Wiring)	\$30,000 Yes	2-Alarms

## Two Alarm Fire

<b>Date of Fire:</b>	March 26, 2009	<b>Time of Fire</b>	3:54 AM												
<b>Incident Number</b>	2009-54734	<b>Response Time</b>	4 Minutes 20 Seconds												
<b>Location</b>	8080 Leigh Ann Drive	<b>Service Area</b>	South Central												
<b>Bldg. Type</b>	2-Story Brick Apartments	<b>Council District</b>	<b>8</b>												
<b>Owner</b>	Larry Burk	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Janet Luckey Leigh Ann Apartments														
<b>Sprinkler System</b>	None	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	No												
<b>Cause</b>	Careless Use of Electric Cook Stove														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$50,000.00</td> <td style="text-align: right;">\$15,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$2,500.00</td> <td style="text-align: right;">\$2,500.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$52,500.00</td> <td style="text-align: right; border-top: 1px solid black;">\$17,500.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$50,000.00	\$15,000.00	Content:	\$2,500.00	\$2,500.00	<b>TOTAL</b>	\$52,500.00	\$17,500.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$50,000.00	\$15,000.00													
Content:	\$2,500.00	\$2,500.00													
<b>TOTAL</b>	\$52,500.00	\$17,500.00													
<b>Narrative</b>	<p>This accidental fire was caused by the careless use of an electric cook stove. The occupant was using the stove for heat. Fire damaged this unit and the attic above it. The unit had a battery operated smoke detector that was non-operational at the time of the fire. There was no sprinkler system for this apartment building. This is an insured loss.</p>														

## One Alarm Fire (Fatality)

<b>Date of Fire:</b>	March 29, 2009	<b>Time of Fire</b>	4:59 AM										
<b>Incident Number</b>	2009-56673	<b>Response Time</b>	34 Seconds										
<b>Location</b>	2842 Britton Avenue	<b>Service Area</b>	South Central										
<b>Bldg. Type</b>	1-Story Frame Dwelling	<b>Council District</b>	4										
<b>Owner</b>	Cheryl Simms	<b>Injuries (Firefighter/Civilian)</b>	Fatality Civilian										
<b>Occupant/ Business Name</b>	Cheryl Simms												
<b>Sprinkler System</b>	None	<b>Operational</b>	N/A										
<b>Fire Alarm System</b>	None	<b>Operational</b>	N/A										
<b>Cause</b>	Careless use of Candles												
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$40,500.00</td> <td style="text-align: right;">\$40,500.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$50,500.00</td> <td style="text-align: right; border-top: 1px solid black;">\$50,500.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$40,500.00	\$40,500.00	Content:	\$10,000.00	\$10,000.00	<b>TOTAL</b>	\$50,500.00	\$50,500.00
	<u>Value</u>	<u>Damage</u>											
Building:	\$40,500.00	\$40,500.00											
Content:	\$10,000.00	\$10,000.00											
<b>TOTAL</b>	\$50,500.00	\$50,500.00											
<b>Narrative</b>	<p>This accidental fire was caused by the careless use of candles. Fire destroyed this dwelling and contents. One fire fatality occurred as a result of this fire. Moses Jones, a 59 year old black male was pronounced dead at the scene. The Medical Examiner listed the cause of death as smoke inhalation. There was no fire alarm system or sprinkler system for this dwelling. Locked burglar bars hindered the escape of the victim and other occupant of this dwelling. This is not an insured loss.</p>												

**One Alarm Fire  
(Smoke Detector Save)**

<b>Date of Fire:</b>	March 30, 2009	<b>Time of Fire</b>	12:06 PM												
<b>Incident Number</b>	2009-57439	<b>Response Time</b>	5 Minutes 6 Seconds												
<b>Location</b>	5606 Arlington Park Drive	<b>Service Area</b>	Northwest												
<b>Bldg. Type</b>	1-Story Frame Dwelling	<b>Council District</b>	2												
<b>Owner</b>	Santos Areyano	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Santos Areyano														
<b>Sprinkler System</b>	None	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Electrical Short Circuit (Appliance)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$52,940.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$1,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$62,940.00</td> <td style="text-align: right; border-top: 1px solid black;">\$6,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$52,940.00	\$5,000.00	Content:	\$10,000.00	\$1,000.00	<b>TOTAL</b>	\$62,940.00	\$6,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$52,940.00	\$5,000.00													
Content:	\$10,000.00	\$1,000.00													
<b>TOTAL</b>	\$62,940.00	\$6,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the household clothes dryer. Fire damaged the laundry room and exterior wall of this dwelling. The dwelling had an operational fire alarm system that warned the sleeping occupant and aided in her escape from the dwelling. There was no sprinkler system for this dwelling. Insurance information is unknown at this time. The response time was delayed because the first up engine company's station is under construction and relocated at another station.</p>														

### Three Alarm Fire

<b>Date of Fire:</b>	April 3, 2009	<b>Time of Fire</b>	2:02 AM												
<b>Incident Number</b>	2009-59765	<b>Response Time</b>	1 Minute 10 Seconds												
<b>Location</b>	5921 Harvest Hill Road #2087	<b>Service Area</b>	North Central												
<b>Bldg. Type</b>	2-Story Stucco Condominiums	<b>Council District</b>	<b>13</b>												
<b>Owner</b>	Noah M. and Lilia A. Liwag, Naza Keserovic, Irfran Pozderac, Weimin Zhu	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Noah Liwag, Steven Harrmann, Emir Huvijar, Weimin Zhu Garden Homes of Preston Place Condominiums														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$200,000.00</td> <td style="text-align: right;">\$200,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$40,000.00</td> <td style="text-align: right;">\$17,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$240,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$217,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$200,000.00	\$200,000.00	Content:	\$40,000.00	\$17,000.00	<b>TOTAL</b>	\$240,000.00	\$217,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$200,000.00	\$200,000.00													
Content:	\$40,000.00	\$17,000.00													
<b>TOTAL</b>	\$240,000.00	\$217,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring in the attic of this building. All four units of this building were damaged by fire. Each unit is individual owned. The condominium had an operational fire alarm system, but since the fire was in the attic space, the system did not warn the occupants nor aid in their escape. There was no sprinkler system for these condominiums. This is an insured loss for the structure, but all tenants reported that they have no renters insurance.</p>														

## Two Alarm Fire

<b>Date of Fire:</b>	April 4, 2009	<b>Time of Fire</b>	9:48 PM												
<b>Incident Number</b>	2009-61025	<b>Response Time</b>	2 Minutes 4 Seconds												
<b>Location</b>	3132 Norwalk Avenue #312	<b>Service Area</b>	Northwest												
<b>Bldg. Type</b>	3-Story Stucco Apartments	<b>Council District</b>	<b>6</b>												
<b>Owner</b>	Singh Family International	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Dwayne Henderson Big Block Apartments														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	No	<b>Operational</b>	N/A												
<b>Cause</b>	Careless Smoking														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$500,000.00</td> <td style="text-align: right;">\$6,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$3,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$510,000.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$9,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$500,000.00	\$6,000.00	Content:	\$10,000.00	\$3,000.00	<b>TOTAL</b>	<b>\$510,000.00</b>	<b>\$9,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$500,000.00	\$6,000.00													
Content:	\$10,000.00	\$3,000.00													
<b>TOTAL</b>	<b>\$510,000.00</b>	<b>\$9,000.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by careless smoking. The tenant fell asleep while smoking a cigarette. Fire damage was contained to the bedroom of this apartment. There was no fire alarm system or sprinkler system for this apartment building. This is not an insured loss.</p>														

### Three Alarm Fire

<b>Date of Fire:</b>	April 7, 2009	<b>Time of Fire</b>	2: 43 PM												
<b>Incident Number</b>	2009-62717	<b>Response Time</b>	3 Minutes												
<b>Location</b>	5930 Arapaho Road #2003	<b>Service Area</b>	North Central												
<b>Bldg. Type</b>	2-Story Frame Apartments	<b>Council District</b>	11												
<b>Owner</b>	Prestonwood Springs LP.	<b>Injuries (Firefighter/ Civilian)</b>	Injury Firefighter												
<b>Occupant/ Business Name</b>	Robert Coleman Monaco Apartments														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Unknown												
<b>Cause</b>	Combustibles Too Close To Heat Source														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$9,300,000.00</td> <td style="text-align: right;">\$700,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$130,000.00</td> <td style="text-align: right;">\$63,500.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$9,430,000.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$763,500.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$9,300,000.00	\$700,000.00	Content:	\$130,000.00	\$63,500.00	<b>TOTAL</b>	<b>\$9,430,000.00</b>	<b>\$763,500.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$9,300,000.00	\$700,000.00													
Content:	\$130,000.00	\$63,500.00													
<b>TOTAL</b>	<b>\$9,430,000.00</b>	<b>\$763,500.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by combustibles too close to a heat source. The occupant left a clothes iron unattended that ignited the sofa in this apartment. Six apartment units were damaged by this fire. A fire alarm was installed but it is unknown if it was operational at the time of the fire. There was no sprinkler system for this apartment building. This is an insured loss.</p>														

### Three Alarm Fire (Smoke Detector Save)

<b>Date of Fire:</b>	April 20, 2009	<b>Time of Fire</b>	09:15 AM												
<b>Incident Number</b>	2009-71116	<b>Response Time</b>	13 Seconds												
<b>Location</b>	1321 Commerce Street	<b>Service Area</b>	Central												
<b>Bldg. Type</b>	24-Story Brick Hotel	<b>Council District</b>	<b>14</b>												
<b>Owner</b>	Adolphus Association J.V.	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Adolphus Hotel Adolphus Hotel														
<b>Sprinkler System</b>	Yes	<b>Operational</b>	Yes												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Mechanical Malfunction														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$4,300,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$2,500,000.00</td> <td style="text-align: right;">\$6,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$6,800,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$6,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$4,300,000.00	\$0.00	Content:	\$2,500,000.00	\$6,000.00	<b>TOTAL</b>	\$6,800,000.00	\$6,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$4,300,000.00	\$0.00													
Content:	\$2,500,000.00	\$6,000.00													
<b>TOTAL</b>	\$6,800,000.00	\$6,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified mechanical malfunction of an industrial gas powered clothes dryer. This fire started in the laundry room, in the sub-basement, underneath the parking garage. This high-rise hotel is equipped with an operational fire alarm system and an operational fire sprinkler system. The fire alarm system warned the occupants and aided in their escape. This fire was too small to activate the sprinkler system. This is an insured loss.</p>														

## Two Alarm Fire

<b>Date of Fire:</b>	April 26, 2009	<b>Time of Fire</b>	05:01 PM												
<b>Incident Number</b>	2009-75499	<b>Response Time</b>	2 Minutes 20 Seconds												
<b>Location</b>	1636 W. Mockingbird Lane	<b>Service Area</b>	Northwest												
<b>Bldg. Type</b>	1-Story Tilt Wall Commercial	<b>Council District</b>	<b>2</b>												
<b>Owner</b>	Dimitrios Papathanasiu	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Luigis Restaurant Luigis Restaurant														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$759,030.00</td> <td style="text-align: right;">\$100,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$250,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$1,009,030.00</b></td> <td style="text-align: right; border-top: 1px solid black;"><b>\$110,000.00</b></td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$759,030.00	\$100,000.00	Content:	\$250,000.00	\$10,000.00	<b>TOTAL</b>	<b>\$1,009,030.00</b>	<b>\$110,000.00</b>	
	<u>Value</u>	<u>Damage</u>													
Building:	\$759,030.00	\$100,000.00													
Content:	\$250,000.00	\$10,000.00													
<b>TOTAL</b>	<b>\$1,009,030.00</b>	<b>\$110,000.00</b>													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring. The wiring was connected to the roof top HVAC unit. Fire consumed the tar covered roof and fell down into the occupancy causing damage to the contents. The building had an operational fire alarm system, however the building was unoccupied at the time of this fire. There was no sprinkler system for this commercial occupancy. This is an insured loss.</p>														

### Four Alarm Fire

<b>Date of Fire:</b>	May 3, 2009	<b>Time of Fire</b>	10:21 PM												
<b>Incident Number</b>	2009-80728	<b>Response Time</b>	2 Minutes 27 Seconds												
<b>Location</b>	4950 Wadsworth Drive #2089	<b>Service Area</b>	South Central												
<b>Bldg. Type</b>	2-Story Frame Apartments	<b>Council District</b>	<b>5</b>												
<b>Owner</b>	Wadsworth Apartments, Inc.	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Kenneth Hunter Oakwood Place Apartments														
<b>Sprinkler System</b>	None	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	Yes	<b>Operational</b>	Yes												
<b>Cause</b>	Incendiary														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$300,000.00</td> <td style="text-align: right;">\$150,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$230,000.00</td> <td style="text-align: right;">\$50,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$530,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$200,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$300,000.00	\$150,000.00	Content:	\$230,000.00	\$50,000.00	<b>TOTAL</b>	\$530,000.00	\$200,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$300,000.00	\$150,000.00													
Content:	\$230,000.00	\$50,000.00													
<b>TOTAL</b>	\$530,000.00	\$200,000.00													
<b>Narrative</b>	<p>This incendiary fire was caused by an unknown person or persons. There are no suspects or witnesses at this time and this fire is under investigation. The fire was started in the listed apartment of origin and spread across the attic causing damage to ten apartment units. The apartments were equipped with a fire alarm system, however the occupants observed smoke prior to alarm activation. There was no sprinkler system for this apartment building. This is an insured loss.</p>														

## Two Alarm Fire

<b>Date of Fire:</b>	May 4, 2009	<b>Time of Fire</b>	02:11 AM												
<b>Incident Number</b>	2009-80836	<b>Response Time</b>	5 Minutes 17 Seconds												
<b>Location</b>	5220 Duncanville Road	<b>Service Area</b>	Southwest												
<b>Bldg. Type</b>	1-Story Masonry Commercial	<b>Council District</b>	<b>3</b>												
<b>Owner</b>	Rafael Lupian	<b>Injuries (Firefighter/ Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Fiesta Gardens Fiesta Gardens														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	No	<b>Operational</b>	N/A												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$415,000.00</td> <td style="text-align: right;">\$100,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$100,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$515,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$110,000.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$415,000.00	\$100,000.00	Content:	\$100,000.00	\$10,000.00	<b>TOTAL</b>	\$515,000.00	\$110,000.00		
	<u>Value</u>	<u>Damage</u>													
Building:	\$415,000.00	\$100,000.00													
Content:	\$100,000.00	\$10,000.00													
<b>TOTAL</b>	\$515,000.00	\$110,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified electrical short circuit of the fixed wiring. Fire ignited the attic insulation and caused damage to the structural members. There was no fire alarm system or sprinkler system for this commercial occupancy. This is an insured loss. The response time was delayed because an incorrect address given by the caller reporting this fire.</p>														

## One Alarm Fire (Injury)

<b>Date of Fire:</b>	May 4, 2009	<b>Time of Fire</b>	05:02 PM												
<b>Incident Number</b>	2009-81198	<b>Response Time</b>	2 Minutes 40 Seconds												
<b>Location</b>	3916 Clover Lane	<b>Service Area</b>	Northwest												
<b>Bldg. Type</b>	1-Story Brick Dwelling	<b>Council District</b>	<b>13</b>												
<b>Owner</b>	Danny Earnest	<b>Injuries (Firefighter/ Civilian)</b>	Injury Firefighter												
<b>Occupant/ Business Name</b>	Danny Earnest														
<b>Sprinkler System</b>	No	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	No	<b>Operational</b>	N/A												
<b>Cause</b>	Incendiary														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 20%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$225,200.00</td> <td style="text-align: right;">\$150,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$150,000.00</td> <td style="text-align: right;">\$15,000.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$375,200.00</td> <td style="text-align: right; border-top: 1px solid black;">\$165,000.00</td> </tr> </tbody> </table>		<u>Value</u>	<u>Damage</u>	Building:	\$225,200.00	\$150,000.00	Content:	\$150,000.00	\$15,000.00	<b>TOTAL</b>	\$375,200.00	\$165,000.00		
	<u>Value</u>	<u>Damage</u>													
Building:	\$225,200.00	\$150,000.00													
Content:	\$150,000.00	\$15,000.00													
<b>TOTAL</b>	\$375,200.00	\$165,000.00													
<b>Narrative</b>	<p>This incendiary fire was caused by an unknown person or persons. There are no suspects or witnesses at this time and this fire is under investigation. Firefighter Marcus Moorehead was injured by falling embers that caused a second degree burn to the back of his neck and bruised his right eye. There was no fire alarm system or sprinkler system for this dwelling. This is an insured loss.</p>														

## Two Alarm Fire

<b>Date of Fire:</b>	May 10, 2009	<b>Time of Fire</b>	02:27 AM												
<b>Incident Number</b>	2009-84844	<b>Response Time</b>	22 Seconds												
<b>Location</b>	5909 Birchbrook Drive #214	<b>Service Area</b>	Northeast												
<b>Bldg. Type</b>	2-Story Brick Condominiums	<b>Council District</b>	<b>14</b>												
<b>Owner</b>	Birchbrook Drive Association LLC	<b>Injuries (Firefighter/Civilian)</b>	N/A												
<b>Occupant/ Business Name</b>	Vacant La Cima Condominiums														
<b>Sprinkler System</b>	None	<b>Operational</b>	N/A												
<b>Fire Alarm System</b>	None	<b>Operational</b>	N/A												
<b>Cause</b>	Unspecified Electrical Short Circuit (Fixed Wiring)														
<b>Value/ Damage Estimate</b>	<table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$30,000.00</td> <td style="text-align: right;">\$30,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td><b>TOTAL</b></td> <td style="text-align: right; border-top: 1px solid black;">\$30,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$30,000.00</td> </tr> </tbody> </table>			<u>Value</u>	<u>Damage</u>	Building:	\$30,000.00	\$30,000.00	Content:	\$0.00	\$0.00	<b>TOTAL</b>	\$30,000.00	\$30,000.00	
	<u>Value</u>	<u>Damage</u>													
Building:	\$30,000.00	\$30,000.00													
Content:	\$0.00	\$0.00													
<b>TOTAL</b>	\$30,000.00	\$30,000.00													
<b>Narrative</b>	<p>This accidental fire was caused by an unspecified short circuit of the fixed aluminum wiring. This fire started in the attic above the bathroom. The fire destroyed this vacant unit. There was no fire alarm system or sprinkler system for these condominiums. This is an insured loss.</p>														