## Dallas Landmark Commission Landmark Nomination Form

1. Name			
historic		vitch House	
and/or common	Concrete Ho	use	
2. Location			
address	523 Eads	land survey Elizabeth Rol	
location/neighbo	rhood Old Oak Cliff	block,lot,tract 4 trac	ct size 95x100
3. Current 2	Zoning		
	НС		
4. Classific	ation		- 2. 2. 3
Category district building(s) structure object	Ownership public both Public Acquisition in progress being considered	Status       Present Use        occupied      agriculture         X_unoccupied      commercial        work in progress      educational         Accessible      entertainment         yes: restricted      government         yes: unrestricted      industrial         X_no      military	museum park residence religious scientific transportation other
5. Ownershi	ip		
Current Owner:	Jess S. Epps, Jr.		
	UC33 J. LPP39 VI.	Phone: 871-8871	and the second
Address: 3109		Dallas State: TX Zip Code:	: 75204
	Carlisle #103 City		: 75204
6. Form Pre	Carlisle #103 City	Dallas State: TX Zip Code:	
	Carlisle #103 City	Dallas State: TX Zip Code:	: 75204 presentativ
6. Form Pre Name & Title Contact	Carlisle #103 City	Dallas State: TX Zip Code: Organization Owner's Re Phone 871-8871	
6. Form Pre Name & Title Contact	Carlisle #103 City eparation Mary Beth Dunning station on Existing State (citywide) _X localstate CBD)ABC esourcehighmedi X	Dallas       State: TX       Zip Code:         Organization       Owner's Re         Phone       871-8871         Irveys	presentativ ter listoric Ldmk
<ul> <li>6. Form Prevent State</li> <li>Name &amp; Title</li> <li>Contact</li> <li>7. Represent</li> <li>Alexander Survey</li> <li>H.P.L. Survey (0)</li> <li>1985 Historic Rest</li> <li>Oak Cliff</li> <li>Victorian Survey</li> <li>1987 Historic Rest</li> </ul>	Carlisle #103 City eparation Mary Beth Dunning station on Existing State (citywide) _X localstate CBD)ABC esourcehighmedi X y esourcehighmedi	Dallas       State: TX       Zip Code:         Organization       Owner's Re         Phone       871-8871         Irveys	presentativ ter fistoric Ldmk ical Ldmk
<ul> <li>6. Form Prevent Strike</li> <li>Name &amp; Title</li> <li>Contact</li> <li>7. Represent</li> <li>Alexander Survey</li> <li>H.P.L. Survey (0)</li> <li>1985 Historic Rest</li> <li>Oak Cliff</li> <li>Victorian Survey</li> <li>1987 Historic Rest</li> </ul>	Carlisle #103 City eparation Mary Beth Dunning itation on Existing Survey Verify (citywide) _X localstate CBD)A_B_C esourcehighmedi X` esourcehighmedi X` For O Survey Verify	Dallas       State: TX       Zip Code:         Organization       Owner's Re         Phone       871-8871         Irveys	presentativ ter fistoric Ldmk ical Ldmk

H#239

11.	. Historic Ownership	
-	original owner Joe Kovandovitc significant later owner(s)	ch
12.		-
	original 1914	
	alterations/additions	15:
13.	. Architect	·
	original construction Joe Kovandovito	ch
	alterations/additions	
14.	. Site Features	
	natural sloping terrain	n
	urban design	
15.	5. Physical Description	
	Condition Check One: excellent X_deteriorated gooduins	Check One: original site moved (date:)

Describe present and original (if known) physical appearance; include style(s) of architecture, current condition and relationship to surrounding fabric (structures, objects, etc.). Elaborate on pertinent materials used and style(s) of architectural detailing, embellishments and site details.

The house sits on sloping terrain on the northern edge of Oak Cliff and has a commanding view of downtown Dallas from the third story. The property backs up to Interstate 35, and access to this block of Eads is gained from the south on Eighth Street or Sixth Street by way of the interstate's access road. The house occupies a large corner lot; unfortunately, there are no other homes existing on neighboring lots for comparison of size and style.

The design of the house resembles a small Italian villa, and also reminds one of a Greek temple. The most distinguishing feature of the structure is the primary building material. Concrete was used exclusively to form the shell of the structure. Kovandovitch mixed sawdust or wood chips into the concrete for insulation.

The main entrance of the house is marked by a portico with a vaulted roof supported by two pairs of symmetrical fluted columns of Ionic order. The same roof line is repeated on the third story. There is an amazing amount of intricate detail on the exterior, which is in sharp contrast to the usually featureless characteristics of concrete. The most notable is the delicate frieze of cupids running across the front which continues across the northern elevation.

The back of the house on the same level features a grand portico, extending almost the entire width of the house. Its slanting slab roof is supported by five Ionic columns and two Doric columns at either end. This portico is on the same level as the front entrance, but because of the sloping nature of the property, the porch is actually a balcony. Continuation Sheet Concrete House

Item # 15

## Page 2 of 2

The lowest level, resembling a walk-out basement, is exposed on three sides of the house, with entrances on all. The south-side entry repeats the vaulted roof and columns. On the north side, there is a short flight of steps leading up to a landing and the back portico. The landing has two freestanding columns of differing heights, which at one time supported a pergola covered with honeysuckle vines. An outside metal staircase, added in 1948 when the house became a multi-family dwelling, leads from the landing to the third story.

The third story is one room, about one-third the width of the other floors, and extends the depth of the house. The windows are large and rectangular, which is characteristic of most of the other windows in the house.

The roof of the second story or main floor is flat and extends on either side of the third story. The gently sloping grade of the roof could be part of an air-conditioning system that Kovandovitch reportedly designed, whereby water flowed over the roof and down the sides. Although the system's existence seems to be commonly accepted, it cannot be confirmed by inspection of the building, research of available records, or discussion with family members.

Unfortunately a fire gutted the interior in 1984, destroying the windows and doors. The structure is sound and the exterior details are intact. The concrete retaining wall that outlines the property is in good condition; the garage, however, is deteriorated.

### 16. Historical Significance

Statement of historical and cultural significance. Include: cultural influences, special events and important personages, influences on neighborhood, on the city, etc.

Because of its close proximity to Interstate 35, the Joe Kovandovitch home or the "Concrete House" as it is more commonly known, has elicited interest from passersby for many years. Its unique site and manner of construction is significant, and the home is an expression of one man's lifelong interest in art, architecture and philosophy.

Whether Joe Kovandovitch intended his home to be a "temple", as son Nick Kovandovitch calls it, or an Italian villa, he definitely wanted to build a place that would stand forever, an idea reinforced by his belief in reincarnation. Perhaps he thought he might return there in another life.

Joe Kovandovitch came to Dallas when he was 15, having come to Texas from Czechoslovakia when he was 13. He married the daughter of frank Wokaty, a resident of Dallas. They had six children; three sons and a daughter still live in Dallas. At the time <u>Czech Pioneers of the Southwest</u> was published in 1934, Kovandovitch had the distinction of being the oldest Czech resident in Dallas. He died at age 86 in 1951.

Over the years, Joe Kovandovitch had several business interests. He was involved in real estate and owned a cafe in downtown Dallas. He was a self-educated man, according to his sons, and had no formal training as an architect; yet, he designed and single-handedly built the "Concrete House". Through his reading, he became fascinated with the use of concrete as a building material. Kovandovitch built a prototype of sorts on Ross Avenue in the early 1910's. As the first solid-concrete structure in Dallas, it received front-page coverage in the Dallas Times Herald. The two-story home was torn down in 1972. One of the sons remembers his father carrying the concrete in buckets up the ladder to the second story in order to pour it into the forms. A daughter recalls that her father, aided by Mrs. Kovandovitch, used a pulley system to raise the buckets at the "Concrete House".

There may have been several reasons why Joe Kovandovitch chose the hillside location on the northern edge of Oak Cliff. Some family members recall their father saying he "wanted to watch Dallas grow." Commuting to town was not a problem, as the Dallas Consolidated Street Railway and a suburban line of the Southern Traction Company, an electric interurban line, had stops nearby.

### 17. Bibliography

City of Dallas Building Permits Office, Dallas, Texas Permits #: 23963 (4/24/33); 74421 (6/;5/33); 44535 (7/1/37); 65531 (1/31/41); 90174 11/13/44); 28836 (5/31/48).

18. Attachments

District or Site map Site Plan Photos (historic & current)

### Continuation Sheet Concrete House

### Item # 16

## Page 2 of 2

Kovandovitch may have felt that the panoramic view from the third story would be an inspiration for his art and writing. <u>The Historic and Architectural</u> <u>Survey of Oak Cliff</u> notes that other artists seem to have been attracted to the area as well. El Sibil, the studio of artist Frank Reaugh, was located just a few blocks away, and watercolorist Edward Eisenlohr lived at 324 Eads.

After a few years, Kovandovitch sold the Oak Cliff house and moved his family back to Ross Avenue, apparently because he felt the streetcar ride to his downtown cafe was too long.

Another interesting owner of the "Concrete House" was a recluse named Eddie Osment. For years he lived without electricity, water, plumbing, and cooking facilities. Because he was considered incompetent, he had a guardian, whose husband brought Eddie food once a day, when he was able.

After years of living in squalor, Eddie was moved to a nursing home. Before the new owner, Jess Stimpson Epps, Jr., closed on the property, the house was gutted by fire. Fortunately, the structure's architecturally significant features--the concrete shell and columns and the band of cupids--remain intact.

The current owner has plans to restore the house and convert it into office space for his architectural firm.

4051T/51T

Continuation Sheet Con

Concrete House

Item # <u>17</u>

### Page <u>2</u> of <u>2</u>

Dallasights: An Anthology of Architectural and Open Spaces, Dallas Chapter of the AIA, 1978, 117.

"Endangered Species: Valuable Texas Architecture Jeopardized by Progress", <u>Texas Homes</u>, September 1980, 43.

Historic and architectural Survey of Oak Cliff, prepared by Alan Mason for the Old Oak Cliff Conservation League, Inc., Dallas, Texas, 1980, 13.

Joe Holley, "Landmarks That Should Be Saved", <u>D Magazine</u>, August 1977, 72.

Estelle Hudson and Henry R. Marsh, Czech Pioneers of the Southwest, South-West Press, Inc., Dallas, Texas, 1934, 338.

Leo Kovan, son of Joe Kovandovitch, Dallas, Texas, telephone conversation--November 12, 1987.

J.F. Kovandovitch, son of Joe Kovandovitch, Dallas, Texas, telephone conversation--August 21, 1987.

Nick Kovandovitch, son of Joe Kovandovitch, Dallas, Texas, telephone conversation--August 21, 1987.

Anna Palmer, daughter of Joe Kovandovitch, Dallas, Texas, telephone conversation--November 12 and 13, 1987.

Sanborn's Insurance Maps, 1921, Vol. 5, page 507.

"Save the Landmarks", <u>D Magazine</u>, October 1984, 114.

Martin Schulz, plumber, Dallas (Oak Cliff), Texas, telephone conversation November 12, 1987.

Worley's General Directory of Dallas, Texas, 1912, 698.

4051T/51T

### APPENDIX PRESERVATION CRITERIA

#### KOVANDOVITCH HOUSE

The Joe Kovandovitch house has been damaged by fire, so that no elements remain except fragments of window and door frames, and the concrete walls. The following criteria shall serve as guidelines for Landmark Commission review of any restoration, replication or renovation of the building. All repairs, replacements or renovations shall conform to the following guidelines:

#### 1. Surface Materials

Any reconstruction, renovation or repair of opaque elements of each building elevation shall employ only brick, concrete, stucco or other masonry similar to the original material in texture, grain, color and module size. Friezes, capitals and other detailing originally executed in concrete shall be retained and, if possible, carefully restored.

### 2. Fenestrations and Openings

Existing door and window openings on each elevation shall remain intact and be preserved. Original window and door configurations and mullion and light patterns shall be replicated, following thorough research and investigation as to original conditions. No reflective or tinted glass will be permitted in window or door openings on any part of the facades.

#### 3. <u>Roof</u>

The slope and configuration of the existing roof shall be preserved and maintained. All existing extensions, parapets and railings shall be preserved and maintained, with the exception of the iron fire escape on the rear elevation, which may be removed. No rooftop mechanical equipment shall be allowed.

### 4. <u>Color</u>

The original whitewash color of the concrete stucco exterior shall be retained or replicated. Paint colors of window and door frames and other non-masonry elements should be based upon any available documentation as to original conditions, and shall be reviewed for compatibility in the Certificate of Appropriateness process.

# 5. Additions and New Construction

No additions or new construction, other than patio, deck or other low-scale site improvements, shall be permitted in the no build zone. All additions or new construction on the remainder of the site shall be reviewed for compatibility through the Certificate of Appropriateness review process.

## 6. Landscaping, Lighting and Signs

Exterior lighting, landscaping, fencing and other site improvements shall be reviewed for compatibility prior to commencement of work. All new exterior signs shall be designed to be compatible with the architectural qualities of the existing structure, and shall be reviewed and approved through the Certificate of Appropriateness process prior to the issuance of a sign permit.

## 7. Public Improvements

All proposed public improvements of streets and associated R.O.W. abutting the site shall be reviewed and approved through the Certificate of Appropriateness process.

## 8. <u>Removal of Accessory Buildings</u>

Proposals to remove accessory buildings on the site shall be reviewed through the Certificate of Appropriateness process.

### **Designation Merit**

A. Character, interest or value as part of the development, heritage or cultural characteristics of the City of Dallas, State of Texas or the United States. Х

- B. Location as the site of a significant historical event
- C. Identification with a person or persons who significantly contributed to the culture and development of the city.
- D. Exemplification of the cultural, economic, social or historical heritage of the city
- E. Portrayal of the environment of a group of people in an era of history characterized by a distinctive architectural style
- F. Embodiment of distinguishing characteristics of an architectural type or specimen
- G. Identification as the work of an architect or master builder whose individual work has influenced the development of the city

### Recommendation

The Designation Task Force requests the Landmark Commission to deem this nominated landmark meritorious of designation as outlined in Chapter 51 and Chapter 51A, Dallas Development Code

Further, the Designation Task Force endorses the Preservation Criteria, policy recommendations and landmark boundary as presented by the Department of Planning and Development H. Embodiment of elements of architectural design, detail, materials or craftsmanship which represent a significant architectural innovation X


- I. Relationship to other distinctive buildings, sites or areas which are eligible for preservation according to a plan based on historic, cultural or architectural motif
- J. Unique location of singular physical characteristics representing an established and familiar visual feature of a neighborhood, community or the city
- K. Archaeological value in that it has produced or can be expected to produce data affecting theories of historic or prehistoric value
- L. Value as an aspect of community sentiment or public pride


1 December 1987 Date:

& metchell he

Debra Mitchell, Chairman Designation Ask Force

Ron Emrich, Senior Planner Historic Preservation





## HISTORIC LANDMARK NOMINATION FORM CITY OF DALLAS LANDMARK COMMITTEE

•

NOTI	E: See attached instructions for completing this form
1.	NAME: a) Historic name of property JOE KOVANDOVITCH HOUSE
	b) Common name of property CONCRETE HOUSE AND CEMENT HOUSE
2.	LOCATION: a) City address: 523 EADS AVE d) Land survey name: ELIZABETH ROBERTSON
	b) Location in city: OAK CLIFF e) Size of tract: 95×100 = 0.218 AC
	c) Neighborhood name: CLIFF HILL f) Block, lot, tract: SEE ABOVE
3.	CURRENT ZONING: HC = HEAVY COMMERCIAL
4.	CLASSIFICATION(CHECK ALL APPROPRIATE):Present UseCategoryOwnershipStatusPresent Usedistrictpublicoccupiedagriculturebuilding(s)privateounoccupiedgovernmentstructurebothwork in progresseducationalobjectin progressyes: restrictedgovernmentbeing considerednomilitaryother
5.	(SOLE) CURRENT OWNER: JESS SEPPS JR PHONE: 871-8871 ADDRESS: 3109 CARLISLE ST # 103 STATE: TX ZIP: 75204 DALLAS
6.	A) NAME AND TITLE: JESS SEPPS JR PRESIDENT-ARCHITECT
	b) ORGANIZATION: EPPS/ARCHITECTS INC
	C) CONTACT PERSON: JESS S EPPS JR PHONE: 871-8871
7.	REPRESENTATION ON EXISTING SURVEYS (CHECK ALL APPROPRIATE IF KNOWN):         • ALEXANDER SURVEY (CITY WIDE)       • LOCAL       STATE       NATIONAL         • BEASLEY H.P.L. SURVEY (CBD)       • A       • B       C       • D         • EMRICH SURVEY (CITY WIDE)       • A       • B       C       • D         • MASON SURVEY (CITY WIDE)       • A       • B       C       • D         • MASON SURVEY (OAK CLIFF)       • MATIONAL REGISTER       • NATIONAL REGISTER         • VICTORIAN STRUCTURE SURVEY       • OTHER:       • OCCCL       MULTIPLE-RESOURCE       NOMINATION       TO       NTL       REGISTER
	FOR OFFICE USE ONLY
	8. FORM RECEIVED: DATE:; SURVEY VERIFIED: Y N; BY:
	9. FORM FIELD CHECKED: DATE:; BY:;
	10. TYPE OF NOMINATION: ARCHEOLOGICALSTRUCTURE(S)DISTRICT SITE ONLYSTRUCTURE AND SITEPETITIONS NEEDED

11. NAME OF ORIGINAL OWNER OF STRUCTURE (\*): JOE FOVANDOVITCH

12. DATE(S) OF ORIGINAL CONSTRUCTION AND MAJOR ALTERATIONS(\*): 1914

- 13. NAME OF ARCHITECTS/CONTRACTORS/OTHERS INVOLVED IN BUILDING DESIGN AND CONSTRUCTION (\*): a) ORIGINAL: JOE FOUNDOUTCH
  - b) ALTERATIONS: NO INFORMATION AVAILABLE

14. NATURAL/URBAN DESIGN FEATURES OF SITE: PANORAMIC VIEW OF DOWNTOWN/ PROMINENT HILL ON MAJOR THOROUGHFARE

15. PHYSICAL DESCRIPTION

Condition:	Check one:		Check one:	
excellent	deteriorated	unaltered	<pre>original site</pre>	
boop	ruins	<pre>altered</pre>	moved date	
fair	unexposed		2	

DESCRIBE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE; INCLUDE STYLE(S) O ARCHITECTURE, CURRENT CONDITION, AND RELATIONSHIP TO SURROUNDING FABRIC (STRUCTURES) PLEASE ELABORATE ON PERTINENT MATERIALS USED AND STYLE(S) OF ARCHITECTURAL DETAILING FO ROOFS, WALLS, WINDOWS, DOORS, AND ANY OTHER BUILDING OR SITE EMBELLISHMENTS O DECORATIONS.

SEE ANNOTATIONS

OPNAMENTAL ITALIANATE FIRIEZE

GREEK COLLONADE

WINDOWS, DOORS AND INTERIOR WERE DESTROYED BY 1984 FIRE. EXTERIOR AND STIRUCTURE REMAIN IN SOUND CONDITION.

OUT-BUILDINGS ARE RUINS AND HAVE NO SIGNIFICANCE

16. HISTORICAL SIGNIFICANCE: STATEMENT OF SIGNIFICANCE, INCLUDE: HISTORY, CULTURAL INFLUENCES, SPECIAL EVENTS AND IMPORTANT PERSONAGES, INFLUENCES ON NEIGHBORHOOD, NEIGHBORHOOD'S INFLUENCE ON THE CITY, ETC.(\*)

UNIQUE PERSONAL EXPRESSION OF A UNIQUE INDIVIDUAL

GATEWAY TO DALLAS FROM SOUTHWEST

EARLY USE OF CAST-IN-PLACE CONCRETE CONSTRUCTION FOR WALLS, FLOORS AND ROOFS

- THIN SHELL DEPRESSED VAULT AIRCH ROOF
- WOOD CHIPS EMBEDGED IN CONCIPETE FOR THEIRMAL INSULATION

EARLY USE OF A FORM OF AN CONDITIONING

· BY WATER FLOWING OVER ROOF AND DOWN WALLS

- 17. ATTACHMENTS (CHECK ALL APPROPRIATE): DISTRICT OR SITE MAP SITE PLAN ANNOTATIONS(\*) DISTRICT OR SITE MAP BIBLIOGRAPHY
- 18. INVENTORY OF STRUCTURES FOR DISTRICTS ONLY, SEE ATTACHED SHEETS. (NOTE: SEE ATTACHED INSTRUCTIONS BEFORE PROCEEDING)

NUMBER OF STRUCTURES: \_\_\_\_\_NUMBER OF ATTACHED SHEETS:\_\_\_

NOT APPLICABLE

(\*) Must be annotated

18.	INVENTORY OF STRUCTURES (DISTRICT NOMINATION ONLY): Pageof
	NAME OF DISTRICT:FORM PREP. BY:
	FOR EACH STRUCTURE IN DISTRICT: a. Address of structure:
	b. Name (if existent):
	c. Architect(s):
	d. Builders(s):
	e. Original owner:
	f. Present owner:
	g. Dominant style:
	h. Condition:
	i. Significant changes to building or site:
	j. Does structure already have State or National historic designation?
	<ul> <li>k. Category (circle one and explain below):</li> <li>1. Contributing - excellent example of an architectural style, and/or designed prominent architect.</li> <li>2. Compatible - supportive of district in age, style, massing, but is not outstand architecture.</li> <li>3. Intrusive - detracts from character of district</li> </ul>
	Explain choice:

1. Describe any out-buildings:


m. Short history and description of structure (may include sketch of grounds):


NOT APPLICABLE

≩ 0.

1/24/85 2606A/161A

### **ENCLOSURE 1**









### BIBLIOGRAPHY

Czech Pioneer Life of the Southwest by Estelle Hudson in Dallas Public Library Re Joe Kovandovitch

D Magazine August 1977, Page 72 "Landmarks that Should Be Saved"

Dallasights An Anthology of Architecture and Open Spaces Dallas Chapter AIA 1978, Page 117

Dallas Historic Landmark Survey Recommended Landmark Sites and Districts Drury Blake Alexander, Architectural Consultant Revised October 1978

Texas Homes September 1980, Page 43 "The Cement House"

Historic and Architectural Survey of Oak Cliff Alan Mason, City Planning Consultant Old Oak Cliff Conservation League Inc. October 1980

D Magazine October 1984, Page 114 "Save the Landmarks"

8 HISTORICAL

PROJECT

D Magazine December 1984, Page 11 LETTERS FROM OUR READERS

**RESTORATION AND** 

PRESERVATION

6

3189 CARLISLE

ST SUITE 103

BALLAS TEXAS

75204 USA

871-8871


AREA 214


EPPS/ARCHITECTS

INC


### APPLICATION FOR NOMINATION AS HISTORICAL LANDMARK


### ENCLOSURE 4







.











.












### APPLICATION FOR NOMINATION AS HISTORICAL LANDMARK

### ENCLOSURE 5







June 13, 1983

Mr. Jess Epps 3109 Carlisle Street Dallas, Texas 75204

Dear Mr. Epps:

I enjoyed talking to you the other day about the Joe Kovandovitch House located at 523 Eads. After looking through our files I found that our information on the building is inadequate, at best. What little information I did find is attached to the letter.

The house is definitely eligible for City landmark designation. I have included a copy of the Dallas Historic Landmark Survey by Drury Alexander which recommends the house for landmark status and ranks it as a second priority building. If you are interested in designating the house as a Dallas historic landmark I will be glad to assist you in the process.

Good luck in your efforts to secure the structure and in it's future renovation. If you have any questions please call me at 670-4133.

Sincerely,

Michael Atwen

Michael Stevens, Urban Planner Program Coordinator, Historic Preservation Department of Planning and Development

рb



November 2, 1984

Mr. Jess Stimpson Epps, Jr. President - Architect 3109 Carlisle Street, Suite 103 Dallas, Texas 75204

Dear Mr. Epps:

RE: Joe Kovandovich House, 523 Eads Street (your letter of 10/18/84)

Thank you for your interest in the historic designation of the above noted house. We support your request and feel certain that the building will be eligible for local designation since it is on our <u>Alexander Survey of Significant Structures</u> <u>in Dallas</u>. That survey, however, only identifies potential buildings, with little background provided. I am enclosing a form for you to use to provide the necessary background research on the building's history. This is needed for our Landmark Committee to make its recommendation to the City Plan Commission and City Council. Once the research is completed, we will work with you to provide the appropriate architectural preservation criteria to provide the restoration parameters for the building. For your reference, I have included a copy of the designation report for the Oak Lawn Methodist Church which includes such criteria.

Regarding the issue of securing the building during this interim period, Mr. Richard Hernandez of the Department of Housing and Neighborhood Services explored an idea with me that seemed to work without damaging the building. He said he would get with you on that.

If I can be of any assistance to you on either of the above items, please do not hesitate to call me at 670-4120.

Sincerely,

Om 1-frederance

Tom Niederauer Development Planning Manager Department of Planning and Development

TN:db

Enclosures

cc: Ray Stanland, Assistant Planning Director Gordon Elliot, Housing and Neighborhood Services Richard Hernandez, Housing and Neighborhood Services



April 7, 1987

Douglas Conners Urban Rehabilitation Standards Board 6DS Dallas City Hall

Dear Mr. Conners:

I am writing concerning the future of 523 Eads. This structure, known as "The Concrete House," was built in 1910 and is a very rare example of poured concrete construction in this early period of Dallas' architectrual history. In the Italian Villa Style, the structure has formal cast concrete front and back columns porticos and a frieze of cupids across the front. It's significance in architecture, Art and engineering has been noted in the Texas Historic Commission's Oak Cliff Survey - 1980, which notes buildings eligible for listing in The National Register of Historic Places.

The Dallas Landmark Commission is concerned that every effort be made to preserve this most important and unique element of our city's history.

Sincerely,

thus White,

Ruthmary White, Chairman of the Landmark Commission

RW:fa

3846T/52T



April 8, 1987

Jess Simpson Epps Jr. 3109 Carlise Dallas, Texas 75204

Dear Mr. Epps:

I am writing concerning the future of 523 Eads. The structure is located in the Texas Historical Commission Survey of Oak Cliff. This survey consists of structures eligible for nomination to the National Regester of Historic Places. The Landmark Commission, of which I am Chairman, would support The Historic Designation of this structure which would allow incentives for it's restoration and reuse.

Sincerely,

full way White

Ruthmary White Landmark Commission Chairman

RW:fa

3848T/55T



April 7, 1987

Mr. Douglas Conner Urban Rehab Standards Board City of Dallas

> RE: Cement House 523 Eads

Dear Mr. Conner:

It is our understanding that we are in danger of losing the cement house at 523 Eads currently owned by Mr. Jess Epps, Jr., 3109 Carlisle Street, Suite 103, Dallas, Texas, 75204.

Long an outstanding landmark in North Cak Cliff, the structure is listed on the Mason Report as one of the 101 outstanding structures, architecturally/ historically, in our area.

Also, the League is in the process of completing a multi-resource nomination to the National Registry and the cement house is included in this nomination.

We need the support of the Board in order to preserve this property in order for Mr. Epps to follow through with his plans for future use, or perhaps find another owner who is in a position at this time to start restoration work immediately.

Yours truly Ruth Chenoweth

Chair, Historic Resources

cc Mr. Ross Ramsey, President, OOCCL

cc: Mr. Jim Anderson, City of Dallas

cc: Mr. Jess Epps, Jr.

-1÷

cc: Mr. Peter Flagg-Maxon Texas Historical Commission HARRY A. GOLEMON, HOUSTON CHAIRMAN GAY RATIJFF, AUSTIN VICE-CHAIRMAN JAMES S. NABORS, SECRETARY LAKE JACKSON

MRS. LUNELLE A. ANDERSON, SAN MARCOS JOHN M. BENNETT, SAN ANTONIO DUNCAN E. BOECKMAN, DALLAS MRS. GEORGE ANN CARTER, FORT WORTH



CORGE CHRISTIAN, AUSTIN **RICHARD H. COLLINS, DALLAS** T.R. FEHRENBACH, SAN ANTONIO MAXINE E. FLOURNOY, ALICE MRS. ALBERT G. HILL, DALLAS DR. ROBERT D. HUNTER, ABILENE MRS. H.L. LONG, KILGORE W. MERRIMAN MORTON, EL PASO LOUIS P. TERRAZAS, SAN ANTONIO EVANGELINE LOESSIN WHORTON. GALVESTON ISLAND DR. DAN A. WILLIS, FORT WORTH

HISTORICAL COMMISSION TEXAS AUSTIN, TEXAS 78711 P.O. BOX 12276

(512) 463-6100

30 April 193

Mr. Douglas Conner Urban Rehabilitation Standards Ecard City of Dallas 1500 Marilla Dallas, Texas 75201

Dear Mr. Conner:

We received a copy of the letter sent to you by Mrs. Ruth Chenoweth of the Old Cak Cliff Conservation League, Inc. regarding the Kovandivitch House at 523 Eads in the North Cak Cliff section of Dallas.

Stylistically and technologically, the Kovandivitch House is of great importance in the Dallas/North Texas context. It is a rare surviving example of a classical villa, and before the construction of IH-35 its siting must have been spectacular. It is also a real rarity ag a cast concrete residence.

We share the concern of many about its current state of neglect, but it appears to maintain its basic design and structural integrity. We believe the structure meets criteria for listing on the National Register of Historic Places, and it is expected to be included in the Historic Resources of Oak Cliff National Register multiple resource nomination.

Thank you for your consideration, and do not hesitate to call us if you have any questions.

Yours truly,

Peter Floring Mayton

Peter Flagg Maxson Senior Architectural Historian

cc: Mrs. Ruth Chenoweth Mr. Jess Epps, Jr. Mr. Ronald Emrich

The State Agency for Historic Preservation