

Memorandum



CITY OF DALLAS

DATE August 21, 2017

TO Honorable Members of the Public Safety Committee:
B. Adam McGough (Chair), Philip T. Kingston (Vice Chair),
Jennifer S. Gates (Domestic Violence Task Force Chair), MPT Dwaine R. Caraway,
DMPT Adam Medrano, Sandy Greyson, Kevin Felder

SUBJECT **Statistical Data / Administrative (Fire) Reports**

This is an informational memo to provide you with a brief description of statistical data and fire reports for May 8, 2017 – July 30, 2017.

Statistical Data for this period:

| <u>Dallas Fire-Rescue Calls</u> | <u>Totals</u> | <u>Percentage</u> |
|---------------------------------|---------------|-------------------|
| Total Incidents | 87,052 | 100% |
| Fire | 14,839 | 17% |
| EMS | 71,757 | 82% |
| Specialize Incidents | 456 | 1% |

Significant fires that occurred during this period:

| <u>Date</u> | <u>Multiple Alarm Level</u> | <u>Number of Units</u> | <u>Personnel</u> | <u>Hours on Scene</u> | <u>Incident Work Hours</u> |
|-------------|-----------------------------|------------------------|------------------|-----------------------|----------------------------|
| 5/13/17 | 2-Alarm | 27 | 69 | 3 | 207 |
| 5/14/17 | 4-Alarm | 49 | 138 | 8 | 1,104 |
| 5/15/17 | 2-Alarm | 30 | 76 | 5 | 380 |
| 6/17/17 | 2-Alarm | 29 | 78 | 1 | 78 |
| 7/7/17 | 2-Alarm | 27 | 79 | 4 | 316 |
| 7/8/17 | 6-Alarm | 67 | 197 | 11 | 2,167 |
| 7/17/17 | 3-Alarm | 33 | 102 | 4 | 408 |
| 7/23/17 | 2-Alarm | 26 | 80 | 6 | 480 |

There were 13 (thirteen) injuries and 2 (two) fatalities that occurred as a result of fire incidents.

The total value of property that received fire damage during this period was \$3,237,350.

The total value of property saved from fire damage during this period was \$46,628,292.

Please contact me if you have any questions or need additional information.



Jon Fortune
Assistant City Manager

[Attachment]

cc: Honorable Mayor and Members of the City Council
T.C. Broadnax, City Manager
Larry Casto, City Attorney
Craig D. Kinton, City Auditor
Rosa A. Rios, City Secretary
Daniel F. Solls, Administrative Judge
Kimberly Bizzor Tolbert, Chief of Staff to the City Manager
Majed A. Al-Ghafry, Assistant City Manager

Jo M. (Jody) Puckett, Assistant City Manager (Interim)
Joey Zapata, Assistant City Manager
M. Elizabeth Reich, Chief Financial Officer
Nadia Chandler Hardy, Chief of Community Services
Raquel Favela, Chief of Economic Development & Neighborhood Services
Theresa O'Donnell, Chief of Resilience
Directors and Assistant Directors

Public Safety Committee

Administrative Fire Reports

Summary

August 2017

| DATE | ADDRESS | COUNCIL DISTRICT | TYPE | CAUSE | LOSS | ALARM |
|-------------|---------------------------------|------------------|----------------------------|--------------|----------------|---------|
| A. 05/11/17 | 1615 Vermont Avenue | 4 (Caraway) | Grass Fire | Incendiary | \$30.00 | 1-Alarm |
| B. 05/13/17 | 18989 Midway Road #106 | 12 (Greyson) | 2-Story Frame Apartments | Undetermined | \$150,800.00 | 2-Alarm |
| C. 05/14/17 | 2410 Logan Street | 7 (Felder) | 1-Story Brick Commercial | Undetermined | \$1,728,180.00 | 4-Alarm |
| D. 05/15/17 | 9690 Forest Lane #701 | 10 (McGough) | 2-Story Frame Dwelling | Undetermined | \$106,700.00 | 2-Alarm |
| E. 06/13/17 | 9808 Valley Meadow Place | 6 (Narvaez) | 2-Story Frame Condos | Accidental | \$8,000.00 | 1 Alarm |
| F. 06/17/17 | 3333 Webb Chapel Extension #310 | 2 (Medrano) | 3-Story Frame Apartments | Accidental | \$115,000.00 | 2 Alarm |
| G. 6/29/17 | 2304 Seedling Lane | 12 (Greyson) | 1-Story Frame Dwelling | Incendiary | \$13,000.00 | 1 Alarm |
| H. 07/07/17 | 1816 Peabody Avenue | 7 (Felder) | 2-Story Frame Dwelling | Incendiary | \$15,000.00 | 2 Alarm |
| I. 07/08/17 | 2663 South Lancaster Road | 4 (Caraway) | 1-Story Brick Commercial | Undetermined | \$420,380.00 | 6 Alarm |
| J. 07/09/17 | 1237 Valley Street | 4 (Caraway) | 1-Story Frame Dwelling | Undetermined | \$22,260.00 | 1 Alarm |
| K. 07/10/17 | 13223 Fish Road #136 | 8 (Atkins) | 1-Story Metal Mobile Home | Undetermined | \$600.00 | 1 Alarm |
| L. 07/14/17 | 12205 Wightman Place | 10 (McGough) | 2-Story Brick Townhouse | Accidental | \$8,000.00 | 1 Alarm |
| M. 07/14/17 | 8029 Chariot Drive #1020 | 7 (Felder) | 2-Story Frame Apartments | Accidental | \$5,000.00 | 1 Alarm |
| N. 07/17/17 | 2900 Walnut Hill Lane | 6 (Narvaez) | 1-Story Masonry Commercial | Undetermined | \$500,000.00 | 3 Alarm |
| O. 07/19/17 | 3811 East Kiest Boulevard #214 | 4 (Caraway) | 2-Story Frame Apartments | Accidental | \$50.00 | 1 Alarm |
| P. 07/23/17 | 542 Pemberton Hill Road | 5 (Callahan) | 2-Story Frame Dwelling | Undetermined | \$109,350.00 | 2 Alarm |
| Q. 07/25/17 | 3595 Ray Road | 8 (Atkins) | 1-Story Frame Dwelling | Accidental | \$35,000.00 | 1 Alarm |

One Alarm Fire (A)

| Date of Fire: | May 11, 2017 | Time of Fire | 6:41 PM | | | | | | | | | | | | |
|---------------------------------------|---|-------------------------|---------------|--------------|---------------|-----------|-------------|--------|----------|---------|---------|--------------|-------------|---------|--|
| Response Time | 3 Minutes 22 Seconds | | | | | | | | | | | | | | |
| Location | 1615 Vermont Avenue | Service Area | South Central | | | | | | | | | | | | |
| Bldg. Type | Grass Fire | Council District | 4 (Caraway) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | No | | | | | | | | | | | | |
| Cause | Incendiary | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$50,000.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$30.00</td> <td style="text-align: right;">\$30.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$50,030.00</td> <td style="text-align: right; border-top: 1px solid black;">\$30.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$50,000.00 | \$0.00 | Content: | \$30.00 | \$30.00 | TOTAL | \$50,030.00 | \$30.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$50,000.00 | \$0.00 | | | | | | | | | | | | | |
| Content: | \$30.00 | \$30.00 | | | | | | | | | | | | | |
| TOTAL | \$50,030.00 | \$30.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an incendiary grass fire that originated in the yard and front porch from a melted plastic gas can. This fire resulted in minimum damage. Engine 23 was the first arriving company.</p> | | | | | | | | | | | | | | |

Two Alarm Fire (B)

| Date of Fire: | May 13, 2017 | Time of Fire | 11:03 PM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|---------------|--------------|---------------|-----------|-----------------|--------------|----------|------------|----------|--------------|-----------------|--------------|--|
| Response Time | 2 Minutes 39 Seconds | | | | | | | | | | | | | | |
| Location | 18989 Midway Road #106 | Service Area | North Central | | | | | | | | | | | | |
| Bldg. Type | 2-Story Frame Apartments | Council District | 12 (Greyson) | | | | | | | | | | | | |
| Business Name | Tivoli Apartments | | | | | | | | | | | | | | |
| Fire Alarm System | Yes | Operational | Yes | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 10%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$12,079,543.00</td> <td style="text-align: right;">\$150,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$5,000.00</td> <td style="text-align: right;">\$800.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$12,084,543.00</td> <td style="text-align: right; border-top: 1px solid black;">\$150,800.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$12,079,543.00 | \$150,000.00 | Content: | \$5,000.00 | \$800.00 | TOTAL | \$12,084,543.00 | \$150,800.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$12,079,543.00 | \$150,000.00 | | | | | | | | | | | | | |
| Content: | \$5,000.00 | \$800.00 | | | | | | | | | | | | | |
| TOTAL | \$12,084,543.00 | \$150,800.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that originated in the attic space above units #105 and #106. The fire spread throughout both units resulting in moderate structural damage. Engine 10 was the first arriving company.</p> | | | | | | | | | | | | | | |

Four Alarm Fire (C)

| | | | |
|---------------------------------------|--|-------------------------|------------|
| Date of Fire: | May 14, 2017 | Time of Fire | 8:37 AM |
| Response Time | 2 Minutes 43 Seconds | | |
| Location | 2410 Logan Street | Service Area | Southeast |
| Bldg. Type | 1-Story Brick Commercial | Council District | 7 (Felder) |
| Business Name | American Fresh Produce | | |
| Fire Alarm System | Unknown | Operational | Unknown |
| Cause | Undetermined | | |
| Value/ Damage Estimate | <u>Value</u> | <u>Damage</u> | |
| | Building: \$1,572,180.00 | \$1,572,180.00 | |
| | Content: \$156,000.00 | \$156,000.00 | |
| | TOTAL \$1,728,180.00 | \$1,728,180.00 | |
| Narrative | This is an undetermined fire that originated in the interior of the structure and traveled to the roof of the building. The fire caused the roof to collapse which resulted in a total loss. Engine 06 was the first arriving company. | | |

Two Alarm Fire (D)

| Date of Fire: | May 15, 2017 | Time of Fire | 3:21 AM | | | | | | | | | | | | |
|---------------------------------------|---|-------------------------|--------------|--------------|---------------|-----------|-----------------|-------------|----------|-------------|-------------|--------------|-----------------|--------------|--|
| Response Time | 2 Minutes 42 Seconds | | | | | | | | | | | | | | |
| Location | 9690 Forest Lane #701 | Service Area | Northeast | | | | | | | | | | | | |
| Bldg. Type | 2-Story Frame Dwelling | Council District | 10 (McGough) | | | | | | | | | | | | |
| 13Business Name | Park Apartments | | | | | | | | | | | | | | |
| Fire Alarm System | Yes | Operational | Unknown | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$22,725,000.00</td> <td style="text-align: right;">\$75,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$58,000.00</td> <td style="text-align: right;">\$31,700.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$22,783,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$106,700.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$22,725,000.00 | \$75,000.00 | Content: | \$58,000.00 | \$31,700.00 | TOTAL | \$22,783,000.00 | \$106,700.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$22,725,000.00 | \$75,000.00 | | | | | | | | | | | | | |
| Content: | \$58,000.00 | \$31,700.00 | | | | | | | | | | | | | |
| TOTAL | \$22,783,000.00 | \$106,700.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that originated in the exterior of apartment unit #701. Upon arrival, firefighters found the front exterior of the structure totally involved. The fire traveled up the walls, onto the building posts and up to units #701, 702, and 707-709 causing moderate structure damage. Engine 29 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (E)

| | | | |
|---------------------------------------|---|-------------------------|-------------|
| Date of Fire: | June 13, 2017 | Time of Fire | 12:43 AM |
| Response Time | 3 Minutes 18 Seconds | | |
| Location | 9808 Valley Meadow Place | Service Area | Northwest |
| Bldg. Type | 2-Story Frame Condo | Council District | 6 (Narvaez) |
| Business Name | Colony Square Condominiums | | |
| Fire Alarm System | No | Operational | No |
| Cause | Accidental | | |
| Value/ Damage Estimate | <u>Value</u> | <u>Damage</u> | |
| | Building: \$74,660.00 | \$6,000.00 | |
| | Content: \$15,000.00 | \$2,000.00 | |
| | TOTAL | \$89,660.00 | \$8,000.00 |
| Narrative | This is an accidental fire that resulted from a heat source too close to combustibles. The fire originated in the kitchen of this unit and caused minor fire and smoke damage. Truck 43 was the first arriving company. | | |

Two Alarm Fire (F)

| Date of Fire: | June 17, 2017 | Time of Fire | 1:25 PM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|-------------|--------------|---------------|-----------|----------------|--------------|----------|-------------|-------------|--------------|----------------|--------------|--|
| Response Time | 1 Minute 51 Seconds | | | | | | | | | | | | | | |
| Location | 3333 Webb Chapel Extension #310 | Service Area | Northwest | | | | | | | | | | | | |
| Bldg. Type | 3-Story Frame Apartments | Council District | 2 (Medrano) | | | | | | | | | | | | |
| Business Name | Villas De Zocalo Apartments | | | | | | | | | | | | | | |
| Fire Alarm System | Yes | Operational | No | | | | | | | | | | | | |
| Cause | Accidental | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$7,548,360.00</td> <td style="text-align: right;">\$100,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$20,000.00</td> <td style="text-align: right;">\$15,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$7,568,360.00</td> <td style="text-align: right; border-top: 1px solid black;">\$115,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$7,548,360.00 | \$100,000.00 | Content: | \$20,000.00 | \$15,000.00 | TOTAL | \$7,568,360.00 | \$115,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$7,548,360.00 | \$100,000.00 | | | | | | | | | | | | | |
| Content: | \$20,000.00 | \$15,000.00 | | | | | | | | | | | | | |
| TOTAL | \$7,568,360.00 | \$115,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an accidental fire that originated in the living room of unit #310. The fire resulted from an unspecified electrical short of fixed wiring. The flames spread to the attic, out to the breezeway, and up to unit #314 resulting in moderate structure damage. Engine 43 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (G)

| Date of Fire: | June 29, 2017 | Time of Fire | 2:26 AM | | | | | | | | | | | | |
|---------------------------------------|---|-------------------------|---------------|--------------|---------------|-----------|--------------|-------------|----------|-------------|------------|--------------|--------------|-------------|--|
| Response Time | 5 Minutes 10 Seconds | | | | | | | | | | | | | | |
| Location | 2304 Seedling Lane | Service Area | North Central | | | | | | | | | | | | |
| Bldg. Type | 1-Story Frame Dwelling | Council District | 12 (Greyson) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | Yes | Operational | Yes | | | | | | | | | | | | |
| Cause | Incendiary | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: right; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$234,569.00</td> <td style="text-align: right;">\$11,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$23,000.00</td> <td style="text-align: right;">\$2,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$257,569.00</td> <td style="text-align: right; border-top: 1px solid black;">\$13,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$234,569.00 | \$11,000.00 | Content: | \$23,000.00 | \$2,000.00 | TOTAL | \$257,569.00 | \$13,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$234,569.00 | \$11,000.00 | | | | | | | | | | | | | |
| Content: | \$23,000.00 | \$2,000.00 | | | | | | | | | | | | | |
| TOTAL | \$257,569.00 | \$13,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an incendiary fire that originated in the kitchen area of the structure. The fire caused minor structure and smoke damage. Engine 10 was the first arriving company.</p> | | | | | | | | | | | | | | |

Two Alarm Fire (H)

| Date of Fire: | July 7, 2017 | Time of Fire | 06:05 AM | | | | | | | | | | | | |
|---------------------------------------|---|-------------------------|------------|--------------|---------------|-----------|-------------|-------------|----------|-------------|------------|--------------|-------------|-------------|--|
| Response Time | 00 Minute 33 Seconds | | | | | | | | | | | | | | |
| Location | 1816 Peabody Avenue | Service Area | Southeast | | | | | | | | | | | | |
| Bldg. Type | 2-Story Frame Dwelling | Council District | 7 (Felder) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | N/A | | | | | | | | | | | | |
| Cause | Incendiary | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$46,140.00</td> <td style="text-align: right;">\$11,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$10,000.00</td> <td style="text-align: right;">\$4,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$56,140.00</td> <td style="text-align: right; border-top: 1px solid black;">\$15,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$46,140.00 | \$11,000.00 | Content: | \$10,000.00 | \$4,000.00 | TOTAL | \$56,140.00 | \$15,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$46,140.00 | \$11,000.00 | | | | | | | | | | | | | |
| Content: | \$10,000.00 | \$4,000.00 | | | | | | | | | | | | | |
| TOTAL | \$56,140.00 | \$15,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an incendiary fire that originated on the exterior. Upon arrival, firefighters found fire and smoke on the rear of the house. The fire resulted in moderate structure damage. Engine 6 was the first arriving company.</p> | | | | | | | | | | | | | | |

Six Alarm Fire (I)

| Date of Fire: | July 8, 2017 | Time of Fire | 9:17 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|---------------|---------------|-----------|--------------|--------------|----------|--------------|--------------|--------------|--------------|--------------|--|--|
| Response Time | 1 Minute 39 Seconds | | | | | | | | | | | | | | |
| Location | 2663 South Lancaster Road | Service Area | South Central | | | | | | | | | | | | |
| Bldg. Type | 1-Story Brick Commercial Building | Council District | 4 (Caraway) | | | | | | | | | | | | |
| Business Name | Wash World | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | No | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$270,380.00</td> <td style="text-align: right;">\$270,380.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$150,000.00</td> <td style="text-align: right;">\$150,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$420,380.00</td> <td style="text-align: right; border-top: 1px solid black;">\$420,380.00</td> </tr> </tbody> </table> | | <u>Value</u> | <u>Damage</u> | Building: | \$270,380.00 | \$270,380.00 | Content: | \$150,000.00 | \$150,000.00 | TOTAL | \$420,380.00 | \$420,380.00 | | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$270,380.00 | \$270,380.00 | | | | | | | | | | | | | |
| Content: | \$150,000.00 | \$150,000.00 | | | | | | | | | | | | | |
| TOTAL | \$420,380.00 | \$420,380.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that is still under investigation. The fire spread to two adjacent businesses (2665 and 2645 (vacant)) before collapsing and resulting in a total loss. Arson investigators were unable to enter the structure due to the instability of the structure. Truck 33 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (J)

| Date of Fire: | July 9, 2017 | Time of Fire | 11:10 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|---------------|--------------|---------------|-----------|-------------|-------------|----------|-------------|-------------|--------------|-------------|-------------|--|
| Response Time | 2 Minutes 08 Seconds | | | | | | | | | | | | | | |
| Location | 1237 Valley Street | Service Area | South Central | | | | | | | | | | | | |
| Bldg. Type | 1-Story Frame Dwelling | Council District | 4 (Caraway) | | | | | | | | | | | | |
| Business Name | Residence | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | No | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: right;"><u>Value</u></th> <th style="text-align: right;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$12,260.00</td> <td style="text-align: right;">\$12,260.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$15,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$27,260.00</td> <td style="text-align: right; border-top: 1px solid black;">\$22,260.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$12,260.00 | \$12,260.00 | Content: | \$15,000.00 | \$10,000.00 | TOTAL | \$27,260.00 | \$22,260.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$12,260.00 | \$12,260.00 | | | | | | | | | | | | | |
| Content: | \$15,000.00 | \$10,000.00 | | | | | | | | | | | | | |
| TOTAL | \$27,260.00 | \$22,260.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that originated in the back bedroom. The fire spread throughout the structure resulting in major damage. Engine 23 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (K)

| Date of Fire: | July 10, 2017 | Time of Fire | 5:06 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|------------|--------------|---------------|-----------|-------------|----------|----------|------------|----------|--------------|-------------|----------|--|
| Response Time | 7 Minutes 02 Seconds | | | | | | | | | | | | | | |
| Location | 13223 Fish Road #136 | Service Area | Southeast | | | | | | | | | | | | |
| Bldg. Type | 1-Story Metal Mobile Home | Council District | 8 (Atkins) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | Yes | Operational | Yes | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$15,600.00</td> <td style="text-align: right;">\$100.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$5,000.00</td> <td style="text-align: right;">\$500.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$20,600.00</td> <td style="text-align: right; border-top: 1px solid black;">\$600.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$15,600.00 | \$100.00 | Content: | \$5,000.00 | \$500.00 | TOTAL | \$20,600.00 | \$600.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$15,600.00 | \$100.00 | | | | | | | | | | | | | |
| Content: | \$5,000.00 | \$500.00 | | | | | | | | | | | | | |
| TOTAL | \$20,600.00 | \$600.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that originated in the living room of the mobile home. The fire caused minor damage to the structure. Engine 09 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (L)

| | | | |
|---------------------------------------|--|-------------------------|--------------|
| Date of Fire: | July 14, 2017 | Time of Fire | 4:32 AM |
| Response Time | 3 Minutes 57 Seconds | | |
| Location | 12205 Wightman Place | Service Area | Northeast |
| Bldg. Type | 2-Story Brick Townhouse | Council District | 10 (McGough) |
| Business Name | N/A | | |
| Fire Alarm System | Unknown | Operational | Unknown |
| Cause | Accidental | | |
| Value/ Damage Estimate | <u>Value</u> | <u>Damage</u> | |
| | Building: \$136,490.00 | \$7,000.00 | |
| | Content: \$15,000.00 | \$1,000.00 | |
| | TOTAL | \$151,490.00 | \$8,000.00 |
| Narrative | <p>This is an accidental fire that resulted from a careless discard of smoking materials. Upon arrival, firefighters reported fire coming from the front door. The fire originated on the living room couch and spread to adjacent combustibles resulting in minor damage. Engine 29 was the first arriving company.</p> | | |

One Alarm Fire (M)

| Date of Fire: | July 14, 2017 | Time of Fire | 10:50 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|------------|--------------|---------------|-----------|----------------|------------|----------|----------|--------|--------------|----------------|------------|--|
| Response Time | 3 Minutes 55 Seconds | | | | | | | | | | | | | | |
| Location | 8029 Chariot Drive #1020 | Service Area | Southeast | | | | | | | | | | | | |
| Bldg. Type | 2-Story Frame Apartments | Council District | 7 (Felder) | | | | | | | | | | | | |
| Business Name | Tshannon Estates | | | | | | | | | | | | | | |
| Fire Alarm System | Unknown | Operational | N/A | | | | | | | | | | | | |
| Cause | Accidental | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$2,751,000.00</td> <td style="text-align: right;">\$5,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$500.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$2,751,500.00</td> <td style="text-align: right; border-top: 1px solid black;">\$5,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$2,751,000.00 | \$5,000.00 | Content: | \$500.00 | \$0.00 | TOTAL | \$2,751,500.00 | \$5,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$2,751,000.00 | \$5,000.00 | | | | | | | | | | | | | |
| Content: | \$500.00 | \$0.00 | | | | | | | | | | | | | |
| TOTAL | \$2,751,500.00 | \$5,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an accidental fire that resulted from a heat source too close to combustibles. Upon arrival, firefighters found smoke showing from the first floor of the complex. The fire spread throughout the unit resulting in minor damage. Engine 32 was the first arriving company.</p> | | | | | | | | | | | | | | |

Three Alarm Fire (N)

| Date of Fire: | July 17, 2017 | Time of Fire | 1:38 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|-------------|--------------|---------------|-----------|----------------|--------------|----------|--------|--------|--------------|----------------|--------------|--|
| Response Time | 1 Minute 31 Seconds | | | | | | | | | | | | | | |
| Location | 2900 Walnut Hill Lane | Service Area | Northwest | | | | | | | | | | | | |
| Bldg. Type | 1-Story Masonry Commercial | Council District | 6 (Narvaez) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | Unknown | Operational | N/A | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 15%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$1,697,580.00</td> <td style="text-align: right;">\$500,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$1,697,580.00</td> <td style="text-align: right; border-top: 1px solid black;">\$500,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$1,697,580.00 | \$500,000.00 | Content: | \$0.00 | \$0.00 | TOTAL | \$1,697,580.00 | \$500,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$1,697,580.00 | \$500,000.00 | | | | | | | | | | | | | |
| Content: | \$0.00 | \$0.00 | | | | | | | | | | | | | |
| TOTAL | \$1,697,580.00 | \$500,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that originated within the roof. The fire caused major damage to the top portion of the building. Engine 43 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (O)

| Date of Fire: | July 19, 2017 | Time of Fire | 8:38 PM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|---------------|---------------|-----------|--------|---------|----------|--------|--------|--------------|--------|---------|--|--|
| Response Time | 3 Minutes 25 Seconds | | | | | | | | | | | | | | |
| Location | 3811 East Kiest Boulevard #214 | Service Area | South Central | | | | | | | | | | | | |
| Bldg. Type | 2-Story Frame Apartments | Council District | 4 (Caraway) | | | | | | | | | | | | |
| Business Name | Kiest Apartments | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | No | | | | | | | | | | | | |
| Cause | Accidental | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 60%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: center;">\$0.00</td> <td style="text-align: center;">\$50.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: center;">\$0.00</td> <td style="text-align: center;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: center; border-top: 1px solid black;">\$0.00</td> <td style="text-align: center; border-top: 1px solid black;">\$50.00</td> </tr> </tbody> </table> | | <u>Value</u> | <u>Damage</u> | Building: | \$0.00 | \$50.00 | Content: | \$0.00 | \$0.00 | TOTAL | \$0.00 | \$50.00 | | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$0.00 | \$50.00 | | | | | | | | | | | | | |
| Content: | \$0.00 | \$0.00 | | | | | | | | | | | | | |
| TOTAL | \$0.00 | \$50.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an accidental fire that resulted from equipment unattended. The fire was contained to the object of origin and resulted in minor smoke damage. Truck 23 was the first arriving company.</p> | | | | | | | | | | | | | | |

Two Alarm Fire (P)

| Date of Fire: | July 23, 2017 | Time of Fire | 4:18 AM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|--------------|---------------|-----------|--------------|--------------|----------|--------|--------|--------------|--------------|--------------|--|--|
| Response Time | 3 Minutes 16 Seconds | | | | | | | | | | | | | | |
| Location | 542 Pemberton Hill Road | Service Area | Southeast | | | | | | | | | | | | |
| Bldg. Type | 2-Story Brick Dwelling | Council District | 5 (Callahan) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | No | Operational | No | | | | | | | | | | | | |
| Cause | Undetermined | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center;"><u>Value</u></th> <th style="text-align: center;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$109,350.00</td> <td style="text-align: right;">\$109,350.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$0.00</td> <td style="text-align: right;">\$0.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$109,350.00</td> <td style="text-align: right; border-top: 1px solid black;">\$109,350.00</td> </tr> </tbody> </table> | | <u>Value</u> | <u>Damage</u> | Building: | \$109,350.00 | \$109,350.00 | Content: | \$0.00 | \$0.00 | TOTAL | \$109,350.00 | \$109,350.00 | | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$109,350.00 | \$109,350.00 | | | | | | | | | | | | | |
| Content: | \$0.00 | \$0.00 | | | | | | | | | | | | | |
| TOTAL | \$109,350.00 | \$109,350.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an undetermined fire that is still under investigation. Upon arrival, firefighters reported fire coming through the roof. The fire caused major smoke and fire damage to the structure causing a total loss. Engine 51 was the first arriving company.</p> | | | | | | | | | | | | | | |

One Alarm Fire (Q)

| Date of Fire: | July 25, 2017 | Time of Fire | 9:08 PM | | | | | | | | | | | | |
|---------------------------------------|--|-------------------------|---------------|--------------|---------------|-----------|-------------|-------------|----------|-------------|-------------|--------------|-------------|-------------|--|
| Response Time | 6 Minutes 18 Seconds | | | | | | | | | | | | | | |
| Location | 3595 Ray Road | Service Area | South Central | | | | | | | | | | | | |
| Bldg. Type | 1-Story Frame Dwelling | Council District | 8 (Atkins) | | | | | | | | | | | | |
| Business Name | N/A | | | | | | | | | | | | | | |
| Fire Alarm System | Unknown | Operational | Unknown | | | | | | | | | | | | |
| Cause | Accidental | | | | | | | | | | | | | | |
| Value/ Damage Estimate | <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 30%;"></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Value</u></th> <th style="text-align: center; border-bottom: 1px solid black;"><u>Damage</u></th> </tr> </thead> <tbody> <tr> <td>Building:</td> <td style="text-align: right;">\$45,000.00</td> <td style="text-align: right;">\$25,000.00</td> </tr> <tr> <td>Content:</td> <td style="text-align: right;">\$25,000.00</td> <td style="text-align: right;">\$10,000.00</td> </tr> <tr> <td>TOTAL</td> <td style="text-align: right; border-top: 1px solid black;">\$70,000.00</td> <td style="text-align: right; border-top: 1px solid black;">\$35,000.00</td> </tr> </tbody> </table> | | | <u>Value</u> | <u>Damage</u> | Building: | \$45,000.00 | \$25,000.00 | Content: | \$25,000.00 | \$10,000.00 | TOTAL | \$70,000.00 | \$35,000.00 | |
| | <u>Value</u> | <u>Damage</u> | | | | | | | | | | | | | |
| Building: | \$45,000.00 | \$25,000.00 | | | | | | | | | | | | | |
| Content: | \$25,000.00 | \$10,000.00 | | | | | | | | | | | | | |
| TOTAL | \$70,000.00 | \$35,000.00 | | | | | | | | | | | | | |
| Narrative | <p>This is an accidental fire that resulted from an unspecified electrical short in non-fixed wiring. The fire spread to nearby combustibles and resulted in major fire and smoke damage throughout the structure. Engine 54 was the first arriving company.</p> | | | | | | | | | | | | | | |