



PARKING ANALYSIS
 VEHICLE OR ENGINE REPAIR OR MAINTENANCE - (3200 S.F.)
 1 SPACE PER 500 S.F. = 6.4 SPACES REQUIRED
 TOTAL EXTERIOR PARKING = 5 SPACES
 TOTAL INTERIOR PARKING PROVIDED = 2 SPACES*
 TOTAL PARKING PROVIDED = 7 SPACES
 * INTERIOR PARKING SPACES ARE NOT USED FOR REPAIR

ADDITIONAL SIGN STATING
 "VIOLATORS SUBJECT TO
 FINE AND TOWING" W/ MIN.
 1" LETTERS BELOW ACCESSIBLE
 PARKING SIGN NO LOWER THAN
 48" ABOVE PARKING SURFACE.

VAN ACCESSIBLE PARKING
 SIGN MOUNTED ON GALV.
 METAL POLE AT 5'-0" A.F.F.

**J DEAN DEKKER
 ARCHITECT**
 6722 NORTHPORT
 DALLAS, TEXAS 75230
 jddekker56@gmail.com
 214-549-4747



A **SITE PLAN - 8505 SAN MARINO**
 1" = 20'-0"

07/28/21