The Traffic Safety and Field Operations Divisions worked in collaboration with other City departments to bring improvements in the community of Five Mile Creek to address illegal dumping, graffiti on DART and City signs, driver visibility challenges, inadequate draining after rains, and severe slope issues with such a rolling terrain.

Our crews:

- Conducted utility locates to prevent damage to existing utilities.
- ♦ Replaced all circular aluminum poles with City standard unistrut poles (square with holes)
- ♦ Replaced all stop signs to the meet the City standard minimum height of 7' with street name blades and street toppers, as well.
- ♦ Affixing red retroreflective tape on all unistrut poles.
- \diamond Replaced all street name blades to the standard minimum height of 9.3".
- ♦ Installed directional and warning signs at several intersections and bends in the roads
- Updated the road striping and marking at/around the intersection of S. Lancaster Road and Givendale Road and past the top of the hill.











